

PROJECT:

Flowline Reel Assessment

under-promise
over-deliver

CLIENT:

Apache Energy Limited

LOCATION:

Carnarvon Basin, WA

DATE:

2010



Linch-pin carried out the full condition survey and structural assessment of the “out-of service” flowline reel to carry 250t of flowline recovered from the Legendre Field.

Scope included:

- Project management.
- As-built survey.
- As-built drawings.
- Corrosion assessment and plate gauging.
- Weld inspection.
- Structural analysis.
- Repairs.
- Preparation for transport.
- Engineering and inspection reports.
- 3rd party lifting compliance certificate.

